

## Troubleshooting for ISA DAQ card

### *Driver initiation failed in Windows 2000/XP/2003.*

Since Windows 2000 WDM architecture requires driver to support Plug-and-Play (PnP) mechanism, but the ISA card hardware does not design for PnP at all. Thus, Windows 2000 cannot detect ISA cards automatically, and users have to add device(s) into Device-Manager manually before running related programs.

Please refer to the “*PCI\_ISA\_PnP\_Driver\_Installation\_in\_Win9x\_2K\_XP.pdf*” file for adding new device(s) into Device-Manager.