

Revision history for DCON_CE_XP

Last update:

V604[2010-Apr-21] by Martin

New support:

None

Modifications:

None

Fixed Bug:

1. Can't configure checksum enable module in XP-8000-CE6

COM2~COM5

DCON Utility:

Must be version 5.1.8 or later

Note: DCON_CE.exe rename to DCON_CE_XP.exe

All revision Information:

V604[2010-Apr-21] by Martin 1

V601 [2008-Jun-15] by Martin5

V601 [2008-Jun-15] by Martin

First release

New support:

Configure I-7000 and I-87K DCON modules on the XP-8000-CE6

COM1 ~ COM 5 via Ethernet

Modifications:

None

Fixed Bug:

None

DCON Utility:

Must be version 5.0.6 or later