

# VP-x20x CE 7.0 OS Update History

Release Date: 11/05/2018

## Key Features:

Features	Supported	Description
Windows CE 7.0 Core OS	Yes	
OS Language	Yes	<b>VP-x20x-ML:</b> Multi-language <ul style="list-style-type: none"><li>- English</li><li>- German</li><li>- Russian</li><li>- French</li><li>- Spanish</li><li>- Italian</li><li>- Korean</li><li>- Simplified Chinese</li><li>- Traditional Chinese</li></ul>
.NET Compact Framework 3.5	Yes	V3.5.7283.0 for Visual Studio .Net 2008
SQL CE 3.5	Yes	SQL CE 3.5 (3.5.5386.0)
FTP Server	Yes	
HTTP Server	Yes	
Telnet	Yes	
Printer	No	
Display Resolution	Yes	800*480 : VP-2201 800*600 : VP-3201 、VP-4201 、VP-5201 1024*768 : VP-6201
Touch Panel	Yes	

## Software and Hardware Compatibility

Software		Hardware	
OS	Eboot	VP-2201	VP-3201、VP-4201、VP-5201、VP-6201
V1.0.1.9 [11/05/2018]	V1.3.4.1	Yes	Yes
V1.0.1.7 [04/23/2018]	V1.3.3.1	Yes	Yes
V1.0.1.6 [03/15/2018]	V1.3.3.1	Yes	Yes
V1.0.1.3 [03/02/2016]	V1.2.1.0	-	Yes
V1.0.1.2 [05/10/2016]	V1.2.1.0	Yes	-

# Table of Contents

- VP-x20x OS 1.0.1.9 - Release Notes [11/05/2018].....4
- VP-x20x OS 1.0.1.7 - Release Notes [04/23/2018].....5
- VP-x20x OS 1.0.1.6 - Release Notes [03/15/2018].....6

# VP-x20x OS 1.0.1.9 - Release Notes [11/05/2018]

## Abstract

This release fixes the problem that when the system time confused, the system time will be corrected to the most recently set time by the OS and the driver of "System\_disk" to reduce the file write errors.

## Bug Fixes

- Fix the driver of "System\_disk" to reduce the file write errors.
- Fix the problem. When the back plane battery loses power to occur the system time confused. The system time will be corrected to the most recently set time to avoid the SNTP server running fail.
- Fix the driver of SD card that auto-mount fail after the SD card hot-plug.

## Eboot 1.3.4.1 [11/09/2018]

- Slow down the flash read/write speed to reduce the file write errors in system disk.

## Software and Hardware Compatibility

Software		Hardware	
OS	Eboot	VP-2201	VP-3201 、 VP-4201 、 VP-5201 、 VP-6201
V1.0.1.9 [11/05/2018]	V1.3.4.1	Yes	Yes

## PAC Utility and PACSDK

- PACSDK DLL                      Version 4.4.1.1    (Released on 09/13/2018)
- PAC Utility                        Version 1.2.2.4    (Released on 08/13/2018)

## VP-x20x OS 1.0.1.7 - Release Notes [04/23/2018]

### Abstract

This release fix the problem of COM3 cannot be used in the VP4201 、VP5201 、VP6201.

### Fix Bug

- Fix the problem of COM3 cannot be used in the VP4201 、VP5201 、VP6201.

### Eboot 1.3.3.1

- No change.

### Software and Hardware Compatibility

Software		Hardware	
OS	Eboot	VP-2201	VP-3201 、VP-4201 、VP-5201 、VP-6201
V1.0.1.7 [04/23/2018]	V1.3.3.1	Yes	Yes

### PAC Utility and PACSDK

- PACSDK DLL           Version 4.4.0.7   (Released on 11/06/2017)
- PAC Utility           Version 1.2.2.1   (Released on 11/07/2016)

# VP-x20x OS 1.0.1.6 - Release Notes [03/15/2018]

## Abstract

This release adds support the VP-2201

## New Features

- Adds support VP-2201
- FTP server adds support REST command -> resume file transfers after interruption

## Eboot 1.3.3.1

- Adds support VP-2201

## Software and Hardware Compatibility

Software		Hardware	
OS	Eboot	VP-2201	VP-3201 、 VP-4201 、 VP-5201 、 VP-6201
V1.0.1.6 [03/15/2018]	V1.3.3.1	Yes	Yes

## PAC Utility and PACSDK

- PACSDK DLL            Version 4.4.0.7    (Released on 11/06/2017)
- PAC Utility            Version 1.2.2.1    (Released on 11/07/2016)