

Revision information for I-8000 firmware

Last update:

Firmware	Interface	SRAM required	CPU speed	Version
8K232.exe	RS-232	128K bytes	40MHz	A2.xx
8K485.exe	RS-485	128K bytes	40MHz	A2.xx

A2.01[2004-Dec-27] by Martin

New support: None

Modifications: None

Bug Fixes:

i-87041 unit's single channel bit output can not work properly.

None