

## Revision information for I-8000 firmware

### Last update:

Firmware	Interface	SRAM required	CPU speed	Version
8K232.exe	Ethernet	256K bytes	40MHz	A2.xx
8K485.exe	Ethernet	256K bytes	40MHz	A2.xx

### A2.01[2004-Dec-27] by Martin

**New support:** None

**Modifications:** None

**Bug Fixes:**

i-87041 unit's single channel bit output can not work properly.