


分類/Classification	<input type="checkbox"/> tDS	<input type="checkbox"/> tGW	<input type="checkbox"/> PETL/tET/tPET	<input checked="" type="checkbox"/> DS/PDS/PPDS	<input type="checkbox"/> tM-752N
	<input type="checkbox"/> I/O Card	<input type="checkbox"/> VXC Card	<input type="checkbox"/> VxComm	<input type="checkbox"/> Other	
作者/Author	Tammy	日期/Date	-	編號/NO.	FAQ-009

Q: Why cannot computer ping or search the PDS series module?

The computer can make a communication with the module through some specific ports. Please confirm with your network administrator that UDP Port 7, Port 23, Port 57188 and Port 54321 can't be denying by network device.



About the detailed information of TCP/UDP port refers to following table:

■ **TCP Port:**

Port Number	Description
80	HTTP (HyperText Transport Protocol)
999	DCON Port
10000	Command Port
10001	Serial Port for COM1
10002	Serial Port for COM2
10003	Serial Port for COM3

■ **UDP Port:**

Port Number	Description
7	Echo (Ping)
23	Command Port
57188	Request of UDP search
54321	Response of UDP search