




1. Run [Start] > [Programs] > [Microsoft Windows Embedded Studio] > [Component Database Manager] > [Import]




2. Browse and choose the PenMount.sld file




3. Press the Import Button and wait for it to finish.



4. If import succeeds, a PenMount Universal Driver Package will appear in the Package tab.



5. Run [Start] > [Programs] > [Microsoft Windows Embedded Studio] > [Target Designer]
6. Open or create a new configuration.
7. Right click on the desired PenMount driver component and add it to the platform configuration.



8. Run [Configuration] > [Check Dependencies (F5)] to add the components that the PenMount device depends on.