

Classification	System and Application FAQ on XPAC					No.	2-012-00
Author	Weikai	Version	1.0.0	Date	2011/3/23	Page	1/3

How to automatically hide the taskbar

Applies to:

Platform	OS version	XPAC utility version
XPAC series	All versions (WinCE6)	All versions

Depending on your preferences, you can set the taskbar to be automatically hidden when the mouse is not over. If to set the taskbar to be automatically hidden, perform the following steps:

Step 1: Set the taskbar to hidden.

1.1. Start the XPAC Utility on the desktop, and then select the “General” tab.



Classification	System and Application FAQ on XPAC				No.	2-012-00	
Author	WeiKai	Version	1.0.0	Date	2011/3/23	Page	2/3

1.2. Check the “Auto Hide” option.



Step 2: Reboot your XPAC.

Classification	System and Application FAQ on XPAC				No.	2-012-00	
Author	Weikai	Version	1.0.0	Date	2011/3/23	Page	3/3

Step 3: After rebooting, the taskbar will be hidden automatically.

