

Revision history for DCON_CE_XP

Note 1:

DCON_CE_XP.exe is only a tool application that help PC site DCON Utility to forward DCON commands to I-87K on backplane or I-87K and I-7K module connected to XPAC-CE6's COM port (COM3 or COM4).

DCON_CE_XP.exe does not support I-8K module configuration function.

Note 2:

We now provide DCON Utility for CE platform which can run on CE platform, it can support most of I-87K/ I-8K modules on backplane and I-87K / I-7K /M-7K modules connected to XPAC-CE6's COM port (COM3 or COM4)..

ftp://ftp.icpdas.com/pub/cd/xp-8000-ce6/system_disk/tools/dcon_utility_ce6/

Last update:

V606 [2012-May-10] by Martin

New support:


None

Modifications:

For old version, DCON_CE_XP.exe does not show I-8K module, from this version, DCON_CE_XP.exe will show I-8K module ID.


Fixed Bug:

When DCON Utility connect RU-87PN via XPAC-CE6 's COM3 or COM4 port as below picture,





If we use RU-87PN's form to configure I/O module, it is under offline condition, for old version, TCP connect will be closed if program does not receive any commands from client over 30 seconds. So after leaving the I/O configuration form, it will lost connection between DCON Utility and DCON_CE_XP.exe



This version fixes this bug.

DCON Utility:

Must be version 5.2.3 or later.

V604[2010-Apr-21] by Martin

New support:

None

Modifications:

None

Fixed Bug:

1. Can't configure checksum enable module in COM2~COM5

DCON Utility:

Must be version 5.1.8 or later

Note: DCON_CE.exe rename to DCON_CE_XP.exe

All revision Information:

V606 [2012-May-10] by Martin.....2

V604[2010-Apr-21] by Martin4

V601 [2008-Jun-15] by Martin.....6

V601 [2008-Jun-15] by Martin

First release

New support:

Configure I-7000 and I-87K DCON modules on the XP-8000-CE6

COM1 ~ COM 5 via Ethernet

Modifications:

None

Fixed Bug:

None

DCON Utility:

Must be version 5.0.6 or later