

Classification	System and Application FAQ on WinCE PAC				No.	2-012-00	
Author	Eric_Shiu	Version	1.0.0	Date	2018/04/27	Page	1/2

How to automatically hide the taskbar


Applies to:

<i>Platform</i>	<i>OS Version</i>	<i>PAC Utility Version</i>
<i>WinPAC</i>	<i>All Versions</i>	<i>All Versions</i>
<i>ViewPAC</i>	<i>All Versions</i>	<i>All Versions</i>


Depending on your preferences, you can set the taskbar to be automatically hidden when the mouse is not over. If to set the taskbar to be automatically hidden, perform the following steps:

Step 1: Set the taskbar to hidden.

1.1. click the "Properties" .



1.2. Check the "Auto Hide" option.



Classification	System and Application FAQ on WinCE PAC				No.	2-012-00	
Author	Eric_Shiu	Version	1.0.0	Date	2018/04/27	Page	2/2

the taskbar will be hidden automatically.

