


WP-9x21-CE7.0 OS 1.1.2.5 Release Notes

Release Date: 11/24/2022

Key Features:

Features	Supported	Description
Windows CE 7.0 Core OS	Yes	
OS Language	Yes	WP-9x21-ML: Multi-language <ul style="list-style-type: none">- English- German- Russian- French- Spanish- Italian- Korean- Simplified Chinese- Traditional Chinese
.NET Compact Framework 3.5	Yes	V3.5.7283.0 for Visual Studio .Net 2008
SQL CE 3.5	Yes	SQL CE 3.5 (3.5.5386.0)
FTP Server	Yes	
HTTP Server	Yes	
Telnet	Yes	
Printer	No	
Display Resolution	Yes	800 x 600, 1024 x 768
Touch Panel	Yes	Support for touch panels using the RS-232 and USB interfaces
Multiport Serial Communication Module  The maximum number of ports that can be used is 16. (i.e., 4slots * 4 ports per module = max. of 16ports)	Yes	Supported modules: I-8112iW (RS-232 *2) I-8114W (RS-232 *4) I-8114iW (RS-232 *4) I-8142iW (RS-485 *2) I-8144iW (RS-485 *4)
Real Time Interrupt	Yes	Interrupt error offset±230µs
3G/4G dial function	Yes	

Software and Hardware Compatibility

Software		Hardware
OS	Eboot	V1.51
V1.1.2.5 [11/24/2022]	V1.3.4.3	Yes
V1.1.2.1 [07/08/2021]	V1.3.4.2	Yes
V1.1.1.9 [12/24/2018]	V1.3.4.1	Yes
V1.1.1.8 [08/02/2018]	V1.3.4.1	Yes
V1.1.0.0 [08/30/2017]	V1.2.2.0	Yes
V1.0.3.1 [05/02/2017]	V1.3.3.0	Yes
V1.0.2.1 [07/14/2016]	V1.2.2.0	Yes
V1.0.1.7 [02/03/2016]	V1.2.2.0	Yes
V1.0.1.4 [12/23/2015]	V1.2.2.0	Yes

Table of Contents

WP-9x21-CE7 OS Version 1.1.2.5 - Release Notes [11/24/2022]4

WP-9x21-CE7 OS Version 1.1.2.5 - Release Notes [11/24/2022]

Abstract

- This release fixes an issue that occurred the Multiport Serial Communication Module cannot work when used the function `serialport.discardinbuffer()` (C#) / `PurgeComm()`(c++), and support DM9119 Ethernet chip driver.

New Features

- Support DM9119 Ethernet chip driver.
- The “Run LED” will flash when setting the LAN1/2 “IP address” by “UDP Search” protocol.

Improvements and Bug Fixes

- Fixes an issue that occurred the Multiport Serial Communication Module I-8144iw/I-8114iw cannot work when used the function `serialport.discardinbuffer()` (C#) / `PurgeComm()`(c++).

Eboot 1.3.4.3 [09/19/2022]

- Support DM9119 Ethernet chip driver.

Software and Hardware Compatibility

Software		Hardware
OS	Eboot	V1.51
V1.1.2.5 [11/24/2022]	V1.3.4.3	Yes

PAC Utility and PACSDK

- PACSDK DLL Version 4.5.0.3 (Released on 03/15/2021)
- PAC Utility Version 1.2.2.6 (Released on 03/15/2021)