Chapter 3: Setting Up A Web HMI Demo

The WinPAC-8xx7 (or WP-8xx7) is the abbreviation of the WinPAC-8147 / 8447 / 8847.

Important:

1. Please always set a **fixed IP** address to the WinPAC-8xx7. (No DHCP) Recommend to use the NS-205 / NS-208 Industrial Ethernet Switch for WinPAC-8xx6/8xx7.

2. The leftmost I/O slot number of the WinPAC is 0.

3.1: Web Demo List

The Web page location:

WinPAC-8xx7 CD-ROM: \napdos\isagraf\wp-8xx7\wp_webhmi_demo\

The respective ISaGRAF project location:

WinPAC-8xx7 CD-ROM: \napdos\isagraf\wp-8xx7\demo\

Demo list:

Name	Description	IO board
sample	A Web HMI sample	No I/O board
	A simple example listed in Chapter 4	slot 0: I-87055W
wphmi_01	Display controller's date & time	No I/O board
wphmi_02	DI & DO demo	slot 0: I-87055W
wphmi_03	Read / Write Long, float & Timer value	No I/O board
wphmi_04	Read / Write controller's String	No I/O board
wphmi_05	Multi-Pages demo	slot 0: I-87055W
	Page menu is on the Left	
wphmi_05a	Multi-Pages demo	slot 0: I-87055W
	Page menu is on the Top	
wphmi_06	AIO demo, scaling is in ISaGRAF	slot 2: I-87024W
		slot 3: I-8017HW
wphmi_07	AIO demo, scaling is in PC	slot 2: I-87024W
		slot 3: I-8017HW
wphmi_08	download controller's file to PC	slot 0: I-87055W
wphmi_09	pop up an alarm window on PC	slot 0: I-87055W
wphmi_11	Trend curve.	slot 2: I-87024W
		slot 3: I-8017hW
wphmi_12	Record 1 to 8 Ch. i8017HW 's volt every 50ms	slot 3: I-8017hW
	and draw trend curve by M.S.Excel	slot 2: I-8024W
wphmi_13	Record 1 to 4-Ch. i8017HW's voltage every	slot 3: I-8017hW
	10ms and draw trend curve by M.S.Excel	slot 2: I-8024W

3.2: Steps To Set Up A Web HMI Demo

3.2.1: Step 1 - Setup The Hardware

A. Please have one WP-8147/8447/8847 and then plug one I-87055W board in its slot 0.

If you don't have the I-87055W (8 IN & 8 OUT board), please follow the same steps as below however your Web HMI demo may be replaced to "wphmi_01" not "wphmi_05"

B. Prepare one VGA monitor, one USB mouse and one ethernet cable and then connect them to the WinPAC-8xx7. (Keyboard is using the software keyboard on the bottom-right of the VGA screen)

C. Power the WinPAC-8xx7 up.

3.2.2: Step 2 - Setting The Web Options

A. Please refer to the Appendix A.3 to set a **fixed IP** address to the WinPAC. (No DHCP)

B. Check on "Enable Web HMI" and then click on "Setting", Please check the "Enable Account Security" and then click on "Edit" to set (username , password). Then remember to click on "OK"

Note: If "Enable Account Security" is not checked, any user can easily get access to your WinPAC through the Internet Explorer.

My Device isqlw35	WinPAC-8x47/8x46 ISaGRAF Driver	OK
desktop rs_wphmi	Enable Web HMI	ibus List IP Setting count Security / level1 ****** Edit dle level2 ****** Edit

3.2.3: Step 3 - Download ISaGRAF Project

Please download ISaGRAF project "wphmi_05" to the WinPAC-8XX7. This project is in the WP-8xx7 CD-ROM:\napdos\isagraf\wp-8xx7\demo\ "wphmi_05.pia"

wphmi_05 demo need one I-87055W.If you don't have the I-87055W (8 IN & 8 OUT board), you may download "wphmi_01" (CD-ROM:\napdos\isagraf\wp-8xx7\demo\ "wphmi_01.pia")

If you know how to restore "wphmi_05.pia" to your ISaGRAF Workbench and download it to the controller, please go ahead to the section 3.2.4.

However if you don't know it, please refer to the below steps. Please make sure the ISaGRAF Workbench is already installed to your PC. (refer to the section 2.1 & 2.2)

Steps To Backing Up & Restoring An ISaGRAF Project:

For archiving purposes you can "Back Up" and "Restore" an ISaGRAF project. For example, you may want someone to test your program or email to <u>service@icpdas.com</u> for ICP DAS's ISaGRAF technical service.

Backing Up An ISaGRAF Project

Open the "ISaGRAF Project Management", select "Tools" from the menu bar, click on "Archive", and then click on "Projects". An "Archive Projects" window will open which allows you to designate where you want to save the ISaGRAF project to. Click on the name of the ISaGRAF project you want to backup, and then click on the "Backup" button. You can compress the size of the file you have backed up by clicking on the "Compress" checkbox BEFORE you click on the "Backup" button.



Then you will now find the backed up ISaGRAF project file in the "Archive" location you have designated. In the example above, the name of the backed up file is "simpleld.pia".

Restoring An ISaGRAF Project

To restore an ISaGRAF project from a backed up file(*.pia), use the same method as above to access the "Archive Projects" window, click on the name of the project you want to restore from the "Workbench" window, then click on the name of the backed up file from the "Archive" window, then click on the "Restore" button. The ISaGRAF project will now be restored to the sub-directory you designated.

Workbench	Archive	
demo_15a 🛛 🛓 demo_15b	simpleId	Backup
demo_16 demo_17		Restore
fbd_exam il_exam io4ld		Close
sfc_exam simpleId		Help
st_exam st_inter work_01		
work_02a work_02b		Compress
Archive location		
C:\SCOTT\		Browse

3.2.3.1: Steps To Download a ISaGRAF Project To The Controller:

Double click on the "wphmi_05" to get into the project. Then click on "Link setup" .



Click on "Setup" first and then entering the IP address of your controller. The port number should be 502.

PC-PLC link para	meters					×
Target Slave N	lumber:	0			<u>0</u> K	
Communication	n port:	ETHER	INET	- <u> </u>	Cancel	
Control					<u>S</u> etup	
Time out	t (seconds):	2			<u> </u>	
Retries:	ETHERNET	ink parame	eters			×
	Internet ad	dress:	10.0.0.103	\sum		<u>o</u> k
	Port numbe	er:	502	\geq		<u>C</u> ancel
	library fo	r TCP-IP c file is correc	ses the WINSC ommunications ctly installed or disk.	s. Ensure		

To download "wphmi_05" project to the WinPAC-8xx7, Click on "Debug". If communication is established, click on "stop" first to stop the old project running in the WP-8xx7.

-SISaGRAF - WPHMI_05 - Programs	
<u>File Make Project Tools Debug Options H</u> elp	
🕒 🖬 😔 🔟 🕒 🖻 🍿 🐺 👗 🕪 💷 🕺 🛛 😫 🔛	
Begin: Image: State of the state of t	
Sequential: SaGRAF - WPHMI_05 - Debugger	
Begin: ST1 (Structured Te: <u>File</u> <u>Control</u> <u>T</u> ools <u>Options</u> <u>H</u> elp	
≫ ► N ► 🗞 🖗 🗭	
'wn yhΩ2' active Stop application	

Then click on "Download" to download it to the controller.

🧟 ISaGRAF - WPHMI_05 - Deb	ougger	
<u>File Control Tools Options Helt</u>	lp	
🐵 碱 🗁 🕨 🕨 🚱	Download	×
'wp_vhl?' active Download	ISA86M: TIC code for Intel Application symbols	
	Download Cancel	

3.2.4: Step 4 - Download Web Pages To The Wincon

A. Please copy all files in the CD-ROM:

WinPAC-8xx7 CD: \napdos\isagraf\wp-8xx7\wp_webhmi_demo\wphmi_05\ *.* to the WinPAC-8Xx7 's \Miscro_SD\Temp\HTTP\WebHMI\

wphmi_05 demo need one I-87055W in its slot 0. If you don't have the I-87055W (8 IN & 8 OUT board), you may download "wphmi_01"

B. Since the Web Pages are modified or new copied, please run "rs_wphmi.exe" to reset the Web server. The "rs_wphmi.exe" must be run every time when user has modified any file in the WP-8xx7 's \Micro_SD\Temp\HTTP\WebHMI\



3.2.5: Step 5 - Show Time

Please run Internet Explorer (Rev. 6.0 or higher), key in the IP address of your WinPAC-8xx7. For example: 61.218.42.10 or http://61.218.42.10

