


# WP-8x21-CE 7.0 OS 1.1.1.9 Release Notes

Release Date: 10/26/2018

## Key Features:

Features	Supported	Description
Windows CE 7.0 Core OS	Yes	
OS Language	Yes	<b>WP-8x21-CE7 ML: Multi-language</b> <ul style="list-style-type: none"><li>- English</li><li>- German</li><li>- Russian</li><li>- French</li><li>- Spanish</li><li>- Italian</li><li>- Korean</li><li>- Simplified Chinese</li><li>- Traditional Chinese</li></ul>
.NET Compact Framework 3.5	Yes	V3.5.7283.0 for Visual Studio .Net 2008
SQL CE 3.5	Yes	SQL CE 3.5 (3.5.5386.0)
FTP Server	Yes	
HTTP Server	Yes	
Telnet	Yes	
Printer	No	
Display Resolution	Yes	800 x 600, 1024 x 768
Touch Panel	Yes	Support for touch panels using the RS-232 and USB interfaces
Multiport Serial Communication Module  <p>The maximum number of ports that can be used is 16. (i.e., 4slots * 4 ports per module = max. of 16ports)</p>	Yes	Supported modules: I-8112iW (RS-232 *2) I-8114W (RS-232 *4) I-8114iW (RS-232 *4) I-8142iW (RS-485 *2) I-8144iW (RS-485 *4)

## Software and Hardware Compatibility

Software		Hardware				
OS	Eboot	V1.80	V1.10	V1.10	V1.91	V1.22
V1.1.1.9 [10/26/2018]	V1.3.4.1	Yes	Yes	Yes	Yes	Yes
V1.1.0.0 [08/08/2017]	V1.2.2.0	Yes	Yes	Yes	Yes	Yes
V1.0.0.3 [07/20/2016]	V1.2.2.0	Yes	Yes	Yes	Yes	No

# Table of Contents

WP-8x21-CE7 OS 1.1.1.9 - Release Notes [10/26/2018] .....4

# WP-8x21-CE7 OS 1.1.1.9 - Release Notes [10/26/2018]

## Abstract

This release fixes the problem that when the system time confused, the system time will be corrected to the most recently set time by the OS and the driver of “System\_disk” to reduce the file write errors.

## Improvements and Bug Fixes

- Fix the driver of “System\_disk” to reduce the file write errors.
- Fix the problem. When the back plane battery loses power to occur the system time confused. The system time will be corrected to the most recently set time to avoid the SNTP server running fail.

## Eboot 1.3.4.1 [10/04/2018]

- Slow down the flash read/write speed to reduce the file write errors in system\_disk.

## Software and Hardware Compatibility

Software		Hardware				
OS	Eboot	V1.80	V1.10	V1.10	V1.91	V1.22
V1.1.1.9 [10/26/2018]	V1.3.4.1	Yes	Yes	Yes	Yes	Yes

## PAC Utility and PACSDK

- PACSDK DLL                      Version 4.4.1.1    (Released on 09/13/2018)
- PAC Utility                        Version 1.2.2.4    (Released on 08/13/2018)